



August 22nd, 2018

Effective Immediately

Subject: Pratt & Whitney 2000/4000/F117 Turbine Case Cooling (TCC) control cable repairs

Reference: CMM 75-24-13 Rev. 13

Dear Valued AeroControlex / Aviall customer,

As the OEM for the PW 2000 / 4000 / F117 Turbine Case Cooling Cable assemblies ACX has created new kits to ensure the highest levels of safety, integrity and reliability of our actuator assembly's. Impacted by this change are the following TCC control assemblies:

P&W P/N	ACX Top Level TCC P/N
59T756	1605140-002
56T761	1605140-001
50U822	1606130-001
56T761-001	1606130-002

AeroControlex has discontinued the individual sale of the rod end bearing (ACX P/N 1600279-001), ball joint assembly (ACX P/N 1600267-001), seal nuts (ACX P/N 1600273-001 and/or 1600273-002) and jam nuts (ACX P/N M62290-4 and/or M62290-6) as individual parts. The individual parts must now be procured as a kit outlined below.

ACX Top Level TCC P/N	New Repair Kit P/N
1605140-002	1609450-002
1605140-001	1609450-001
1606130-001	1609460-001
1606130-002	1609460-002

These kits may be ordered directly from Aviall @ www.aviall.com or (800) 284-2551.